Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/50005DE2183/1
Work Order Type: Weatherization
Audit Name: Audit (4)

CLIENT INFORMATION

Client Name: Address:
Client ID: 50005DE2183 , TN

Alt. Client ID:

AGENCY INFORMATION

 Agency:
 Delta Human Resource Agency
 Agency Phone:
 (901) 476-5226

 Address:
 P. O. Box 634
 Fax:
 (901) 476-5258

Company Name & License Number:	
Contractor's Signature:	

COMMENT

Blower Door could not get a reading to much air infiltrating through holes in the floor and around the door. This is the minimum recommended CFM at 50pa.

Client Name: Client ID: 50005DE2183 Alt. Client ID: Work Order (Bid Form)
Work Order Name: WO/50005DE2183/1
Report Run On: 5/28/2010

DOE Weatherization Assistant Version 8.5.0 Page 1 of 8

Measures

Measu	ıre 1 Ele ga	ectric Water Heater Repla I.)	acement (30	Componen	ıts			Inspected
Comme	ent								
					Estimated	<u> </u>		Actual	
# Materi	al / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Hot W Equip		Material		1					
2 Labor		Labor		1					
Other De	etail								
				Measui	e Sub Total:			Sub Total:	
Measu Comme		por patch by bath 1'x3'			Componen	its			Inspected
		por patch by bath 1'x3'			Componen			Actual	Inspected
Comme		poor patch by bath 1'x3' Description / Comment	Units	Qty	-		Qty		Inspected Total
Comme	ent al/Labor		<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
Comme	ent al/Labor	Description / Comment			Estimated	<u> </u>	Qty	Actual	
# Materia 1 Windo	ent al/Labor ows	Description / Comment Material		1	Estimated	<u> </u>	Qty	Actual	
Comme# Materi1 Windo2 Labor	ent al/Labor ows	Description / Comment Material		1	Estimated	<u> </u>	Qty	Actual	
Comme# Materi1 Windo2 Labor	ent al/Labor ows	Description / Comment Material		1	Estimated	<u> </u>	Qty	Actual	
# Materia 1 Windo 2 Labor	ent al/Labor ows	Description / Comment Material	Each	1 1	Estimated	<u> </u>		Actual	

	or patch by water heate	r 5'x6'		Componen	ts			Inspected
Comment				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Windows	Material	Each	1					
2 Labor	Labor		1					
Other Detail						1		
			Measur	e Sub Total:]]	Sub Total:	
Field Notes:								
Measure 4 Flo	or patch in hallway 8'x3			Componen	ts			Inspected
	or patch in hallway 8'x3	•		Componen Estimated			Actual	Inspected
	oor patch in hallway 8'x3 Description / Comment	Units	Qty	•		Qty		Inspected Total
Comment # Material / Labor				Estimated		Qty	Actual	
# Material / Labor 1 Windows	Description / Comment	Units	Qty	Estimated		Qty	Actual	
# Material / Labor 1 Windows	Description / Comment Material	Units	Qty 1	Estimated		Qty	Actual	
Comment# Material / Labor1 Windows2 Labor	Description / Comment Material	Units	Qty 1	Estimated		Qty	Actual	
Comment# Material / Labor1 Windows2 Labor	Description / Comment Material	Units	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	
Comment# Material / Labor1 Windows2 Labor	Description / Comment Material	Units	Qty 1 1	Estimated			Actual	
Comment# Material / Labor1 Windows2 Labor	Description / Comment Material	Units	Qty 1 1	Estimated Unit Cost			Actual Unit Cost	

Measure 5 Flo	or patch in kitchen 5'x3'	•		Componen	ts		1	Inspecte	
	nenc			Estimated	,	Actual			
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Windows	Material	Each	1						
2 Labor	Labor		1						
Other Detail						1			
			Moasur	e Sub Total:]	Sub Total:		
Field Notes:							L		
Massura 6 Flo	or natch in Living Pm 0			Componen				Inspecte	
	or patch in Living Rm 9'	'x1'		Componen				Inspecte	
Comment				Estimated		Oftv	Actual		
Comment # Material / Labor	or patch in Living Rm 9' Description / Comment Material	'x1' <i>Units</i> Each	Qty 1	•		Qty		Inspecte	
Comment # Material / Labor 1 Windows	Description / Comment Material	Units	Qty 1	Estimated		Qty	Actual		
# Material / Labor Windows Labor	Description / Comment	Units	Qty	Estimated		Qty	Actual		
Comment # Material / Labor 1 Windows	Description / Comment Material	Units	Qty 1	Estimated		Qty	Actual		
# Material / Labor Windows Labor	Description / Comment Material	Units	Qty 1	Estimated		Qty	Actual		
# Material / Labor Windows Labor	Description / Comment Material	Units Each	Qty 1 1	Estimated Unit Cost			Actual		
# Material / Labor 1 Windows 2 Labor Other Detail	Description / Comment Material	Units Each	Qty 1 1	Estimated			Actual Unit Cost		
# Material / Labor Windows Labor	Description / Comment Material	Units Each	Qty 1 1	Estimated Unit Cost			Actual Unit Cost		

	_	place Heating [Gas]			Componen	ts			nspected
U	omment				Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Heating Equipment	Replacement gas furnace	Each	1					
2	Labor	Replacement gas furnace	Each	1					
C	Other Detail]		
				Measur	e Sub Total:] .	Sub Total:	
	Measure 8 Report	place Doors Mandatory			Componen				nspecte
					Estimated	 -		Actual	
	Material / Labor Doors	Description / Comment Replacement doors	Units Each	Qty 1	Unit Cost	Total	Qty	Unit Cost	Total
2	Labor	Replacement doors	Each	1					
C	Other Detail						1		
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Measure 9 Rep	place Doors Mandatory			Componen	ts Front			Inspected
				Estimated	·		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Doors	Replacement doors	Each	1					
2 Labor	Replacement doors	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Measure 10 Bel	lly Fiberglass Loose			Componen				Inspected
# Material / Labor	Description / Comment	Units		Estimated Unit Cost	Total	O41	Actual Unit Cost	Total
1 Insulation	Description / Comment Floor Insulation - Fbergls,Blwn	Bag	Qty 21		rotar	Qty	Omit Cost	TOTAL
2 Labor	Floor Insulation - Fbergls,Blwn	Bag	21					
Other Detail	_							
			Measur	e Sub Total:] .	Sub Total:	
Field Notes:								

Measure 11 Wa	III Fiberglass Loose			Componen	ts			Inspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Wall Insulation - Fbergls,Blwn	Bag	12					
2 Labor	Wall Insulation - Fbergls,Blwn	Bag	12					
Other Detail						7		
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Measure 12 Re	frigerator Replacement			Componen				Inspected
Measure 12 Re Comment		Units	Qtv	Estimated	<u> </u>	Qtv	Actual	
Measure 12 Re Comment # Material / Labor	frigerator Replacement Description / Comment	<i>Units</i> Each	Qty 1	-		Qty		Inspected Total
Measure 12 Re Comment # Material / Labor 0 Refrigerators	Description / Comment			Estimated	<u> </u>	Qty	Actual	
Measure 12 Re Comment # Material / Labor	Description / Comment			Estimated	<u> </u>	Qty	Actual	
Measure 12 Re Comment # Material / Labor 0 Refrigerators	Description / Comment			Estimated	<u> </u>	Qty	Actual	
Measure 12 Re Comment # Material / Labor 0 Refrigerators	Description / Comment	Each	1	Estimated	<u> </u>		Actual	
Measure 12 Re Comment # Material / Labor 0 Refrigerators Other Detail	Description / Comment	Each	1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
Measure 12 Re Comment # Material / Labor 0 Refrigerators	Description / Comment	Each	1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

Report Run On: 5/28/2010

Measure 13 Fix I	mproper Venting (Clot	hes Dryer)	Componen	ıts			Inspected
Comment Replace	Dryer Vent							
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
 Health and Safety Items 	Equipment	Each	1					
2 Labor	Labor	Hour	1					
Other Detail								
			Moasur	e Sub Total:]]	Sub Total:	
Field Notes:			Weasur	e Sub Tolai.			oub rotui.	
Measure 14 Insta Comment	all Kitchen Exhaust Far	า		Componen				Inspected
# 100000001/10000	December / Comment	Unito		Estimated			Actual	Total
# Material / Labor1 Health and Safety Items	Description / Comment Kitchen exhaust fan	<i>Units</i> Each	Qty 1	Unit Cost	Total	Qty	Unit Cost	Total
2 Labor	Labor	Hour	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
		Work Or	der Gra	and Total:		Gran	d Total:	

Report Run On: 5/28/2010